



Wednesday, July 13, 2011

Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL  
Sample ID#s: BA50946 - BA50960

This laboratory is in compliance with the QA/QC procedures outlined in EPA 600/4-79-019, Handbook for Analytical Quality in Water and Waste Water, March 1979, SW846 QA/QC and NELAC requirements of procedures used.

This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory.

A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.

If you have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext. 200.

Sincerely yours,

A handwritten signature in black ink, appearing to read "Phyllis Shiller".

Phyllis Shiller  
Laboratory Director

NELAC - #NY11301  
CT Lab Registration #PH-0618  
MA Lab Registration #MA-CT-007  
ME Lab Registration #CT-007  
NH Lab Registration #213693-A,B  
NJ Lab Registration #CT-003  
NY Lab Registration #11301  
PA Lab Registration #68-03530  
RI Lab Registration #63  
VT Lab Registration #VT11301



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50946

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB01 SOFFIT BRICK JCTN RM 001

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	61		%	07/12/11		MH	40 - 140 %
% TCMX	75		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB B  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50947

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB02 BRICK WINDOW JAM RM001

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	61		%	07/12/11		MH	40 - 140 %
% TCMX	77		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50948

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB03 SOFFIT BRICK JCTN RM 001

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	74		%	07/12/11		MH	40 - 140 %
% TCMX	72		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50949

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB04 SOFFIT BRICK JCTN RM 026

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	81		%	07/12/11		MH	40 - 140 %
% TCMX	77		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50950

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB05 SOFFIT BRICK JCTN RM 027

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	64		%	07/12/11		MH	40 - 140 %
% TCMX	78		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB B  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50951

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB06 BRICK WINDOW JAMB RM 026

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	68		%	07/12/11		MH	40 - 140 %
% TCMX	82		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB B  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50952

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB07 BRICK WINDOW JAMB RM 027

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	84		%	07/12/11		MH	40 - 140 %
% TCMX	82		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB B  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

Date	Time
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50953

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB08 BRICK WINDOW JAMB RM 028

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	67		%	07/12/11		MH	40 - 140 %
% TCMX	84		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

Date	Time
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50954

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB09 SOFFIT BRICK JCTN RM 031

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	67		%	07/12/11		MH	40 - 140 %
% TCMX	84		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB B  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50955

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB10 BRICK DOOR JAMB RM 032

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	66		%	07/12/11		MH	40 - 140 %
% TCMX	82		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50956

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB11 SOFFIT BRICK JCTN RM 032

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	64		%	07/12/11		MH	40 - 140 %
% TCMX	80		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

Date	Time
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50957

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB12 SOFFIT BRICK JCTN RM 037

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C

### Polychlorinated Biphenyls

PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082

### QA/QC Surrogates

% DCBP	68		%	07/12/11		MH	40 - 140 %
% TCMX	84		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50958

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB13 SOFFIT BRICK JCTN RM 039

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	65		%	07/12/11		MH	40 - 140 %
% TCMX	80		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB S  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

Date	Time
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50959

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL

Client ID: 7-11 PCB14 SOFFIT BRICK JCTN RM 040

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	82		%	07/12/11		MH	40 - 140 %
% TCMX	78		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## Analysis Report

July 13, 2011

FOR: Attn: Mr. Ashis Roychowdhury  
Eagle Environmental Inc.  
531 North Main Street  
Bristol, CT 06010

### Sample Information

Matrix: WIPE  
Location Code: EAGLEENV | PCB B  
Rush Request: RUSH24  
P.O.#: 11-082.11

### Custody Information

Collected by:  
Received by: LDF  
Analyzed by: see "By" below

<u>Date</u>	<u>Time</u>
07/11/11	0:00
07/11/11	11:07

### Laboratory Data

SDG ID: GBA50946  
Phoenix ID: BA50960

Project ID: TOWN OF BOLTON BOLTON HIGH SCHOOL  
Client ID: 7-11 PCB15 BRICK DOOR JAMB GYMNASIUM

Parameter	Result	RL	Units	Date	Time	By	Reference
PCB Wipe Extraction	Completed			07/11/11		BB/K	SW-3540C
<b><u>Polychlorinated Biphenyls</u></b>							
PCB-1016	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1221	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1232	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1242	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1248	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1254	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1260	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1262	ND	1.0	ug	07/12/11		MH	SW8082
PCB-1268	ND	1.0	ug	07/12/11		MH	SW8082
<b><u>QA/QC Surrogates</u></b>							
% DCBP	72		%	07/12/11		MH	40 - 140 %
% TCMX	72		%	07/12/11		MH	40 - 140 %

### Comments:

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

ND=Not detected BDL=Below Detection Level RL=Reporting Level

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director  
July 13, 2011



Environmental Laboratories, Inc.  
587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045  
Tel. (860) 645-1102 Fax (860) 645-0823



## QA/QC Report

July 13, 2011

### QA/QC Data

SDG I.D.: GBA50946

Parameter	Blank	LCS %	LCSD %	LCS RPD	MS Rec %	MS Dup Rec %	RPD	% Rec Limits	% RPD Limits
-----------	-------	----------	-----------	------------	-------------	--------------------	-----	--------------------	--------------------

QA/QC Batch 180146, QC Sample No: BA49292 (BA50946, BA50947, BA50948, BA50949, BA50950, BA50951)

#### Polychlorinated Biphenyl

PCB-1016	ND	78	81	3.8				40 - 140	30
PCB-1221	ND							40 - 140	30
PCB-1232	ND							40 - 140	30
PCB-1242	ND							40 - 140	30
PCB-1248	ND							40 - 140	30
PCB-1254	ND							40 - 140	30
PCB-1260	ND	92	92	0.0				40 - 140	30
PCB-1262	ND							40 - 140	30
PCB-1268	ND							40 - 140	30
% DCBP (Surrogate Rec)	84	82	86	4.8				40 - 140	30
% TCMX (Surrogate Rec)	86	81	86	6.0				40 - 140	30

Comment:

A LCS and LCS Duplicate were performed instead of a matrix spike and matrix spike duplicate.

QA/QC Batch 180419, QC Sample No: BA50952 (BA50952, BA50953, BA50954, BA50955, BA50956, BA50957, BA50958, BA50959, BA50960)

#### Polychlorinated Biphenyl

PCB-1016	ND	87	93	6.7				40 - 140	30
PCB-1221	ND							40 - 140	30
PCB-1232	ND							40 - 140	30
PCB-1242	ND							40 - 140	30
PCB-1248	ND							40 - 140	30
PCB-1254	ND							40 - 140	30
PCB-1260	ND	109	115	5.4				40 - 140	30
PCB-1262	ND							40 - 140	30
PCB-1268	ND							40 - 140	30
% DCBP (Surrogate Rec)	76	74	75	1.3				40 - 140	30
% TCMX (Surrogate Rec)	79	81	82	1.2				40 - 140	30

Comment:

A LCS and LCS Duplicate were performed instead of a matrix spike and matrix spike duplicate.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

RPD - Relative Percent Difference

LCS - Laboratory Control Sample

LCSD - Laboratory Control Sample Duplicate

MS - Matrix Spike

MS Dup - Matrix Spike Duplicate

NC - No Criteria

Phyllis Shiller, Laboratory Director

July 13, 2011



# CHAIN OF CUSTODY RECORD

587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06040  
Email: info@phoenixlabs.com Fax (860) 645-0823  
Client Services (860) 645-8726

Temp 73 Pg 1 of 3

Data Delivery:  
☐ Fax #  
☐ Email

Customer: Eagle Environmental, Inc. Project P.O.: 11-082,11  
Address: 531 N. Main St. Report to: Ashis Roychowdhury Phone #: 860-589-0257  
Bristol, Ct. 06010 Invoice to: Brandy LaBlanc Fax #:

## Client Sample Information - Identification

Sampler's Signature: [Signature] Date: 7-11-11

Matrix Code: DW=Drinking Water GW=Ground Water SW=Surface Water WW=Waste Water  
SE=Sediment SL=Sludge S=Soil/Solid W=Wipe O=Other

PHOENIX USE ONLY SAMPLE #	Customer Sample Identification	Sample Matrix	Date Sampled	Time Sampled
50946	7-11-PCB-01 - Soft Fat	W	7-11	AM
50947	Brick Junction - Rm 001	W	7-11	AM
50948	7-11-PCB-02 - Brick	W	7-11	AM
50949	Window Jamb - Rm 001	W	7-11	AM
50950	7-11-PCB-03 - Soft Fat	W	7-11	AM
50951	Brick Junction - Rm 001	W	7-11	AM
50952	7-11-PCB-04 - Soft Fat	W	7-11	AM
50953	Brick Junction - Rm 001	W	7-11	AM
50954	7-11-PCB-05 - Soft Fat	W	7-11	AM
50955	Brick Junction - Rm 001	W	7-11	AM
50956	7-11-PCB-06 - Brick	W	7-11	AM
50957	Window Jamb - Rm 001	W	7-11	AM

Relinquished by: [Signature] Accepted by: [Signature]

Date: 7-11-11 Time: 11:07

RI ☐ Direct Exposure (Residential)  
☐ GW  
☐ Other

CT ☐ RCP Cert  
☐ GW Protection  
☐ SW Protection  
☐ GA Mobility  
☐ GB Mobility  
☐ Residential DEC  
☐ I/C DEC  
☐ Other

MA ☐ MCP Certification  
☐ GW-1  
☐ GW-2  
☐ GW-3  
☐ S-1  
☐ S-2  
☐ S-3  
☐ MWRA eSMART  
☐ Other

Data Format  
☐ Excel  
☐ PDF  
☐ GIS/Key  
☐ EQUIS  
☐ Other

Data Package  
☐ Tier II Checklist  
☐ Full Data Package  
☐ Phoenix Std Report  
☐ Other

Comments, Special Requirements or Regulations:

Turnaround:  
☒ 1 Day\*  
☐ 2 Days\*  
☐ 3 Days\*  
☐ Standard  
☐ Other

\* SURCHARGE APPLIES

State where samples were collected: CT

\* SURCHARGE APPLIES

Analysis Request

GL VOA Vials (methanol) H2O	
GL Soil Container (oz)	
GL Soil Container (oz)	
GL VOA Vial (As is) HCl	
GL As is (250ml) H2SO4	
GL HNO3 250ml	
GL NaOH 250ml	
Bacteria Bottle	



